



February 6, 2025

BSE Limited
Corporate Relationship Department
Phiroze Jeejeebhoy Towers
Dalal Street
Mumbai – 400 001.
Scrip Code: 500400

National Stock Exchange of India Limited
Exchange Plaza, C-1, Block G,
Bandra-Kurla Complex,
Bandra (East)
Mumbai – 400 051.
Symbol: TATAPOWER

Dear Sir/Madam,

Disclosure under Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 - update

Pursuant to Regulation 30 read with Para A of Part A of Schedule III of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015, as amended, and further to our intimation dated October 30, 2024, regarding fire incident occurred at the Cable Vault and subsequently the Control Room of Trombay Plant (Unit 5), we hereby inform you that the production operations at plant (Unit 5) which was temporarily disrupted due to the fire accident has been restored back and remains fully operational, ensuring power supply to the grid.

This is for your information and records.

Yours Sincerely,
For **The Tata Power Company Limited**

Vispi S. Patel
Company Secretary
FCS 7021

TATA POWER

The Tata Power Company Limited

Registered Office Bombay House 24 Homi Mody Street Mumbai 400 001

Tel 91 22 6665 8282 Fax 91 22 6665 8801

Website: www.tatapower.com Email: tatapower@tatapower.com CIN: L28920MH1919PLC000567



Printed on 100% Recycled Paper